# Navajo Abandoned Uranium Mine

# Site Screen Report

This form is for use at the site of abandoned uranium mines (AUM) located on Navajo Nation lands. Applicable sites include all mine and mine features that have or have not undergone reclamation by the Navajo Abandoned Mine Lands Reclamation Program, including features, adits, pits and waste piles. Applicable sites also include all AUM sites listed in the USEPA CERCLIS database, all sites listed in the 2008 AUM GIS Report issued by USACOE and USEPA, all AUM sites on allotment lands associated with the Navajo Nation, and any and all AUM sites not listed in any database located on Navajo lands. Reconnaissance of any sites located on lands adjacent to Navajo lands that may be impacting Navajo lands will need to be coordinated with the authorities appropriate to those lands.

The purpose of the form is to ascertain the status and location of the identified AUM site, and record all immediate site information associated with the mine site. Decisions and recommendations on what additional steps are needed will be provided on a separate document.

Mine Name: **Sunlight**Mine ID: **179** 

Navajo AUM North Central Region

Prepared by:

Weston Solutions, Inc.

Contract: W91238-06-F-0083

20074.063.039.0020

April 2012

Part I	Site Identifica	ation, Location	and Status			
Site Names and ID numbers as applicable						
Mine ID:	179					
Map ID:	NC42					
CERCLIS:	NNN000909246					
Navajo Abandoned Mine Land Reclamation Program: NA-0220						
Local name / Aliases: Sunlight Shaft						
Chapter and local area: Oljato						
County: Nav	ajo	State: AZ				
<b>Lat/Long:</b> 36.9472753789 N / -110.288490869 W						
Nearby road	and highway:	Route 163	<b>Local Post Office:</b>	Oljato, AZ		
Surface Land Status: check one or more and provide ownership and contact information below						
Tribal Trust Private Bureau of La State			Public lands Tribal Fee Land Allotment Fee land			
Subsurface Mineral Rights:						
No information on subsurface mineral rights ownership was found in the EPA/AUM Database.						

e.

# **Claim and operator information:**

Historical documents identified the operator of the mine in 1955 as Roy and Betty Gray, and from 1958 to 1964 as Industrial Uranium Company. No additional historical ownership / lease information was identified in the EPA / AUM database.

Number of residential structures within 200 feet of mine: None

# Part II Summary of Radiological Readings

**Mine ID: 179** 

**Highest gamma radiation measurement:** 659,859 counts per minute (cpm)


**Background Average:** 10,351 cpm **Two Times Background:** 20,702 cpm

# Describe any other radiological measurements:

A total of 3,015 gamma radiation measurements were collected from the mine site, ranging from 7,532 cpm to 659,859 cpm. Maximum levels of approximately 60,000 cpm were found near the tailings, and 650,000 cpm were found near the exposed ore. The measurements are represented in Figures 1 and 2.

#### **Distribution Chart and Statistics:**

<b>Site Gamma Radiation</b>	Statistics
Number of Readings	3,015
Minimum (cpm)	7,532
Maximum (cpm)	659,859
Mean (cpm)	34,933
Median (cpm)	13,608
Standard Deviation	80,183



#### Part III Status of Reclamation and Mine Waste

**Mine ID: 179** 

The following information was obtained from the Navajo Abandoned Mine Land Reclamation Program (NAMLRP) Point Features Database:

NAMLRP Status of the mine site: Reclaimed: Yes Waste Pile onsite: No

**NAMLRP Project Number:** NA-0220

**NAMLRP Mine features:** 1 Vertical

The following information was obtained from field observations collected during the 2011 site screening:

Provide description and status of all mine sites and features at site. Include all waste piles, adits, pits and other features, and indicate whether they are open, closed, covered, capped, buried or unreclaimed. Indicate approximate size, shape and extent, including description of any reclamation caps. Note condition of all caps.

#### Observed reclamation work and status:

#### Adits:

None Observed

#### **Waste Piles:**

None Observed

#### Pits:

None Observed

## **Shafts:**

None Observed

#### **Other Debris and Mine Features:**

Some mining equipment and debris; tailings piles were noted on the Topo, alongside the road; some exposed ore was found in the southern part of the site

#### Part IV Site Observations and Environs

Observed Residential Structures (number and human habitation status of structures at the following distances from the mine site):

0 to 200 feet: None Observed

**200 feet to 0.25 mile:** None Observed

Observed Public or Commercial Structures (schools, clinics, Chapter Houses, places of business and any other structures used by members of the community at the following distances from the mine site):

0 to 200 feet: None observed

**200 feet to 0.25 mile:** None observed

Levels measured around the perimeter(s) of the identified structure(s):

None

Observed Water Sources (number and type of wells and surface water sources that are potentially used for human consumption at the following distances from the mine site):

**0 to 0.25 miles:** 500 ft W - Water Well 8K-433

**0.25 miles to 4 miles:** 0.75 mi S - Well (519)

Sensitive Environments (all sensitive environments located within visible range of the mine site, including: wetlands, endangered species, habitats and approximate locations of sites that may be under protection of the government of the Navajo Nation):

None observed

Known Site History (information from interviews with Chapter officials and residents and database review, includes: mine ownership, type of mining operation, period of operation, known amount of production, and any other information provided):

The Sunlight mine claim consists of an area of 67,704 m<sup>2</sup>. The mine was identified as being operational from 1958 to 1964. While operational, the mine had a total reported production volume of 55,024 tons. No additional historical ownership / lease information was identified in the EPA / AUM database.

# Part V Response Action Summary

## **Summary of Evaluation Factors:**

## Accessibility:

Was the mine easily accessible to potential human activity?

Yes

# Radiological Measurements:

Were any gamma radiation measurements collected at the mine greater than two times the site-specific background levels?

Yes

#### Waste Piles:

Were any unreclaimed waste piles observed at the mine with gamma radiation measurements greater than two times the site-specific background levels?  $\rm No$ 

#### Structures:

Were any structures observed within 200 feet of the mine?

No

## Potential Drinking Water Sources:


Were any potential drinking water sources observed within 4 miles of the mine? Yes

#### Reclamation:


Was the mine reported to be previously reclaimed, or did the mine appear to be reclaimed?

Yes

# Part VI Photos












# Part VII Contact Reports and Information

Name:	Eugene Esplain		
Title or official role (if any):	Navajo EPA Superfund Program		
Telephone number:	(928) 871-7331		
Address:	PO Box 2946, Window Rock, AZ 86515		
Information provided:	Lead Regulatory Agency		
Name:			
Title or official role (if any):			
Telephone number:			
Address:			
Information provided:			
Name:			
Title or official role (if any):			
Telephone number:			
Address:			
Information provided:			

Figure 1 - Gamma Radiation Measurements, Above Two Times Background
Sunlight (179)
Oljato Chapter, Navajo Nation




**Observed Structure** 

**Observed Adit** 

Average background 10,351 cpm


Figure 2 - Gamma Radiation Measurements Sunlight (179) Oljato Chapter, Navajo Nation



#### **Gamma Radiation Measurements**

- 0 10,000 cpm
- 10,000 25,000 cpm
- 25,000 50,000 cpm
- 50,000 100,000 cpm
- 100,000 250,000 cpm
- 250,000 500,000 cpm
- 500,000 1,000,000 cpm

Average background 10,351 cpm



Observed Waste Rock

Observed Structure

Observed Adit

Measured as counts per minute (cpm)

